

Message

---

**From:** Jacqueline Ronstadt [Jacqueline.Ronstadt@pima.gov]  
**Sent:** 12/23/2020 7:24:16 PM  
**To:** Sims, Mark [Sims.Mark@epa.gov]  
**Subject:** FW: Tucson Iron and Metal Dioxin/Furan Retest  
**Attachments:** TIM220419 Dioxin & Furan Retest Report [FINAL].pdf

Mark,

Attached is the performance test retest report from November 24, 2020 for D/F. The testing company calculated the results using TEQ. When the TEQ value is removed the D/F value should be 812 ng/dscm we believe.

Jackie Ronstadt  
PDEQ Air Compliance Manager  
P: 520-724-9726 Ex. 6 Personal Privacy (PP)  
[www.pima.gov/deq](http://www.pima.gov/deq)

---

**From:** Mark Severson <MSeverson@bison-eng.com>  
**Sent:** Tuesday, December 22, 2020 5:24 PM  
**To:** Jacqueline Ronstadt <Jacqueline.Ronstadt@pima.gov>  
**Cc:** Gary Kippur <gary@tucsoniron.net>  
**Subject:** Tucson Iron and Metal Dioxin/Furan Retest

\*\*\*\*\*

This message and sender come from outside Pima County. If you did not expect this message, proceed with caution. Verify the sender's identity before performing any action, such as clicking on a link or opening an attachment.

\*\*\*\*\*

Ms. Ronstadt,

On behalf of Tucson Iron and Metal, Bison Engineering is submitting the November 24, 2020 dioxin and furans retest report. Please confirm that you received this report and let us know if you need any additional information or have questions related to the test results.

Kind Regards,

Mark

Mark Severson, P.E.  
*Arizona Branch Manager*



4251 S Station Master Drive  
Tucson, AZ 85714

O: +1 (520) 749-2167  
D: +1 (520) 989-7704

M: +1 (520) 262-0576

[mseverson@bison-eng.com](mailto:mseverson@bison-eng.com)

<http://www.bison-eng.com>